#### 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

**Building Information** 

BROCKPORT CSD

| Page La: | st Modifie | d: 03/16 | /2016 |
|----------|------------|----------|-------|
|----------|------------|----------|-------|

Name of School District:

| <b>Building Information</b> | Bui | lding | Inform | ation |
|-----------------------------|-----|-------|--------|-------|
|-----------------------------|-----|-------|--------|-------|

| 2.   | SED District 8-Digit BEDS Code: |
|------|---------------------------------|
| 2618 | 801060000                       |
|      | 3. Building Name:               |
|      | Brockport High School           |
|      | 4. SED 4-Digit Facility Code:   |
|      | 0007                            |
|      | 5. Survey Inspection Date:      |
|      | 08/18/2015                      |
|      | 6. Building 911 Address:        |
|      | 40 Allen Street                 |
|      | 7. City:                        |
|      | Brockport                       |
|      | 8. Zip Code:                    |

9. Certificate of Occupancy Status:

☑ A - Annual

14420

- ☐ T Temporary
- □ N None

10. Certificate of Occupancy Expiration Date:

01/01/2017

#### **Building Age, Gross Square Footage and Maintenance Staff**

11. Year of Original Building:

1966

12. Gross square ft. of Building as currently configured:

310,860

13. Number of Floors:

3

14. How many full-time and part-time custodians are employed at the school (or work in the building)?

06/03/2016 09:36 AM Page 1 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

**Building Information** 

| Page  | Last | Modified:   | 03/16/2016 | ว |
|-------|------|-------------|------------|---|
| · uuc | Last | ivioaiiica. | 00/10/2010 | , |

|                       | Count Employees |
|-----------------------|-----------------|
| Full-time custodians: | 10              |
| Part-time custodians: | 3               |
| Totals:               | 13.00           |

#### **Building Ownership and Occupancy Status**

| 9             | company canal   |
|---------------|---|
| 15.           | Building Ownership (check one):   |
| <b>Y</b>      | Owned and used by district  |
|               | Owned by District and leased to non-district entity   |
|               | Owned by District, part used by district, part leased to non-district entity  |
|               |   |
|               | Owned by non-district entity and leased to district   |
| 16            | · · · · · · · · · · · · · · · · · · ·   |
| □<br>16.      | Owned by non-district entity and leased to district  For which of the following purposes is the building currently used? (check all that apply)                       |
| □<br>16.<br>☑ | · · · · · · · · · · · · · · · · · · ·   |
|               | For which of the following purposes is the building currently used? (check all that apply)  |
| <b>=</b>      | For which of the following purposes is the building currently used? (check all that apply)  Used for student instructional purposes                                   |
|               | For which of the following purposes is the building currently used? (check all that apply)  Used for student instructional purposes  Used for district administration |

#### **Building Users**

17. How many students were registered to receive instruction in this building as of October 1, 2014? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)

1,182

18. Of these registered students, how many receive most of their instruction in:

|   | Quantity |
|---|----------|
| 18a. Permanent instructional spaces (i.e., regular classrooms)  | 1182     |
| 18b. Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building | 0        |
| 18c. Non-instructional spaces used as instructional spaces  | 0        |

18c.1 If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2014? (check all that apply)

|   | Cafeteria               |
|---|-------------------------|
|   | Gymnasium               |
|   | Administrative Spaces   |
|   | Library                 |
|   | Lobby                   |
|   | Stairwell               |
|   | Storage space           |
|   | Other (please describe) |
| ~ | None                    |

19. Grades Housed:

9-12

06/03/2016 09:36 AM Page 2 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

**Building Information** 

Page Last Modified: 03/16/2016

| 20. For how many instructional days during the 2013-14 school year (July 1 through June 30, was the building |
|--|
| closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0") |
|  |
| 0  |
| 21. Is the building used for instructional purposes in the summer?   |
| ☑ Yes  |
| □ No   |
|  |
| 22. Have there been renovations or construction in the building during the past 12 months?                   |
| ☑ Yes  |
| □ No   |
|  |
| 23. Was major construction/renovation work since 2010 conducted when school was in session?                  |
| ☑ Yes  |
| □ No   |
|  |

06/03/2016 09:36 AM Page 3 of 48

Labella Associatoes, DPC

# Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| Program Spaces                 |  |  |  |
|--------------------------------|--|--|--|
| Page Last Modified: 03/16/2016 |  |  |  |
| Program                        |  |  |  |
| 24                             | . Number of instructional classrooms:  |  |  |
| 92                             |  |  |  |
| 25                             | . Gross square footage of all instructional classrooms (combined):   |  |  |
| 92,                            | 592.00   |  |  |
| 26                             | . Other spaces provided: (check all that apply)  |  |  |
| Space A                        | □ a. N/A (none) □ j. Health Office □ s. Resource Rooms □ b. Administration □ k. Home & Careers □ t. Science Labs □ c. Art □ l. Kitchen □ u. Special Education □ d. Audio Visual □ m. Large Group Instruction □ v. Swimming Pool □ e. Auditorium □ n. Library □ w. Teacher Resource □ f. Cafeteria □ o. Multipurpose Rooms □ x. Technology/Shop □ g. Computer Room □ p. Music □ y. Other (please describe) □ h. Guidance □ q. Pre-K □ i. Gymnasium □ r. Remedial Rooms  269. Describe other spaces  (No Response) |  |  |
| -                              |  |  |  |
| <b>27</b> . <b>☑</b>           | . Rating of space adequacy:  |  |  |
|                                | Fair   |  |  |
|                                | Poor   |  |  |
|                                | 27a. Enter comments:   |  |  |
|                                | (No Response)  |  |  |
| 28                             | . Estimated capital construction expenses anticipated for this building through 2020-2021 school year  |  |  |
| ex                             | cluding maintenance (to be answered after the building inspection is complete) \$  |  |  |
| 4,5                            | 44,071.00  |  |  |
| 29                             | . Overall building rating (to be answered after the building inspection is complete)   |  |  |
|                                | Excellent  |  |  |
|                                | Satisfactory   |  |  |
|                                | Unsatisfactory Poor  |  |  |
| 30                             | . Was overall building rating established after consultation with health and safety committee?   |  |  |
|                                | Yes  |  |  |
|                                | No   |  |  |
| A/E Infor                      | rmation:   |  |  |
| 31                             | . A/E Firm Name:   |  |  |

06/03/2016 09:36 AM Page 4 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Program Spaces

Page Last Modified: 03/16/2016

| 32.    | A/E Firm Address:      |
|--------|------------------------|
| 300 S  | tate Street, Suite 201 |
|        | ester, NY 14614        |
| 33.    | A/E Firm Phone Number: |
| 58545  | 546110                 |
| 34.    | E-mail:                |
| dpiete | ers@labellapc.com      |
| 35.    | A/E Name:              |
| Danie  | el Pieters             |
| 36.    | A/E License #:         |
| 03292  | 27                     |
|        |                        |

06/03/2016 09:36 AM Page 5 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

06/03/2016 09:36 AM Page 6 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

| Page Last I                          | Modified: 06/02/2016                             |
|--------------------------------------|--|
| 38e                                  | . Cost to reconstruct/Replace \$:                |
|                                      | Response)  |
| 38f.                                 | Comments:  |
| (No                                  | Response)  |
| 39. Site                             | Gas (H)  |
| <ul><li>✓ Yes</li><li>□ No</li></ul> |  |
| 39a                                  | . Type of gas service:                           |
|                                      | Natural Gas<br>Liquid Petroleum                  |
| 39b                                  | . Condition:                                     |
|                                      | Excellent  |
|                                      | Satisfactory Unsatisfactory                      |
|                                      | Non-Functioning Critical Failure                 |
|                                      | . Year of Last Major Reconstruction/Replacement; |
| 1990                                 |  |
|                                      | Expected Remaining Useful Life (Years):          |
| 20                                   |  |
| 39e                                  | . Cost to Reconstruct/Replace \$:                |
|                                      | Response)  |
| 39f.                                 | Comments:  |
| (No                                  | Response)  |
| 40. Site                             | Fuel Oil (H)                                     |
| □ Yes ☑ No                           |  |
| E NO                                 |  |
| 41. Site                             | Electrical, Including Exterior Distribution (H)  |
| ☑ Yes                                |  |
| □ No                                 |  |
|                                      | . Service Provider:                              |
|                                      | Municipal or utility provided Self-Generated     |
|                                      | Other  |
|                                      | N/A  |

06/03/2016 09:36 AM Page 7 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Site Utilities

| Oile Oil | mes  |
|----------|--|
| Page La  | ast Modified: 06/02/2016   |
|          | 41b. Type of Service:  |
|          | <ul> <li>□ Above Ground</li> <li>⊡ Below Ground</li> <li>□ N/A</li> </ul>  |
|          | 41c. Condition:  |
|          | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> </ul>                             |
|          | □ Critical Failure  41d. Year of Last Major Reconstruction/Replacement:  |
|          | 2008   |
|          | 41e. Expected Remaining Useful Life (Years):   |
|          | 43   |
|          | 41f. Cost to Reconstruct/Replace \$:   |
|          | (No Response)  |
|          | 41g. Comments:   |
|          | (No Response)  |
|          | Management   |
| 42. (    | Closed Drainage Pipe Stormwater Management System  |
| 42       | 2a. Does this facility have a closed pipe system?  |
| ☑ Yes    |  |
|          | 42b. Condition:  |
|          | <ul> <li>□ Excellent</li> <li>□ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul> |
|          | 42c. Year of Last Major Reconstruction/Replacement:  |
|          | 2006   |
|          | 42d. Expected Remaining Useful Life (Years):   |
|          | 20   |
|          | 42e. Cost to Reconstruct/Replace \$:   |
|          | 101,930.00   |

06/03/2016 09:36 AM Page 8 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Site Utilities

| One Onnies  | •   |
|-------------|---|
| Page Last I | Modified: 06/02/2016                                      |
| 42f.        | Comments:   |
|             |   |
| Repa        | air drainage- eastern and south lot.                      |
| 43. Oper    | Drainage Pipe Stormwater Management System                |
| 43a. D      | oes this facility have an open stormwater system (ditch)? |
| ✓ Yes       |   |
| □ No        | . Condition:  |
|             | Excellent   |
|             | Satisfactory  |
|             | Unsatisfactory<br>Non-Functioning                         |
|             | Critical Failure  |
| 43c         | . Year of Last Major Reconstruction/Replacement:          |
| 1966        |   |
| 43d         | . Expected Remaining Useful Life (Years):                 |
| 10          |   |
| 43e         | . Cost to Reconstruct/Replace \$:                         |
| (No         | Response)   |
| 43f.        | Comments:   |
| (No         | Response)   |
| 44. Catc    | h Basins/Drop Inlets/Manholes                             |
| 44a. D      | oes this facility have catch basins/drop inlets/manholes? |
|             |   |
| □ No        |   |
|             | . Condition:  |
|             | Excellent<br>Satisfactory                                 |
|             | Unsatisfactory Non-Functioning                            |
|             | Critical Failure  |
| 44c         | . Year of Last Major Reconstruction/Replacement:          |
| 2015        |   |
| 44d         | . Expected Remaining Useful Life (Years):                 |
| 20          |   |
|             |   |

06/03/2016 09:36 AM Page 9 of 48

#### **BROCKPORT CSD**

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Site Utilities

| Page Last Modified: 06/02/2016                             |
|--|
| 44e. Cost to Reconstruct/Replace \$:                       |
| (No Response)  |
| 44f. Comments:   |
| (No Response)  |
| 45. Culverts   |
| 45a. Does this facility have culverts?                     |
| ☐ Yes ☑ No   |
| 46. Outfalls   |
| 46a. Does this facility have outfalls?                     |
| □ Yes □ No   |
| 47. Infiltration Basins/Chambers                           |
| 47a. Does this facility have infiltration basins/chambers? |
| <ul><li>✓ Yes</li><li>□ No</li></ul>                       |
| 47b. Condition:  |
| □ Excellent  |
| <ul><li>✓ Satisfactory</li><li>Unsatisfactory</li></ul>    |
| □ Non-Functioning □ Critical Failure                       |
| 47c. Year of Last Major Reconstruction/Replacement:        |
| 2005   |
| 47d. Expected Remaining Useful Life (Years):               |
| 20   |
| 47e. Cost to Reconstruct/Replace \$:                       |
| (No Response)  |
| 47f. Comments:   |
| (No Response)  |
| 48. Retention Basins                                       |
| 49a Daga this facility have retention begins?              |
| 48a. Does this facility have retention basins?  ☐ Yes      |
| ☑ No   |

Page 10 of 48 06/03/2016 09:36 AM

Status Date: 12/16/2015 10:45 AM **BROCKPORT CSD** 

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

Page

| Li | ast | Modified: 06/02/2016   |  |  |  |  |  |  |
|----|-----|--|--|--|--|--|--|--|
|    | 49. | 49. Wetponds   |  |  |  |  |  |  |
|    |     | 49a. Does this facility have wetponds?   |  |  |  |  |  |  |
|    |     | Yes<br>No  |  |  |  |  |  |  |
|    |     |  |  |  |  |  |  |  |
|    | 50. | . Manufactured Stormwater Proprietary Units  |  |  |  |  |  |  |
|    |     | 50a. Does this facility have proprietary units?  |  |  |  |  |  |  |
|    |     | Yes  |  |  |  |  |  |  |
|    | ✓   | No   |  |  |  |  |  |  |
|    |     |  |  |  |  |  |  |  |
|    | 51. | Point of Outfall Discharge: (check all that apply)   |  |  |  |  |  |  |
|    |     | Municipal storm sewer system   |  |  |  |  |  |  |
|    |     | Combined sewer system  |  |  |  |  |  |  |
|    |     | Surface Water  |  |  |  |  |  |  |
|    |     | On-site recharge   |  |  |  |  |  |  |
|    |     | Other (describe)   |  |  |  |  |  |  |
|    | ✓   | Not Applicable   |  |  |  |  |  |  |
|    | 52. | . Outfall Reconnaissance Inventory   |  |  |  |  |  |  |
|    |     | Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge? |  |  |  |  |  |  |
|    | П   | Yes  |  |  |  |  |  |  |
|    |     | No No  |  |  |  |  |  |  |
|    | ✓   | Not Applicable   |  |  |  |  |  |  |

Page 11 of 48 06/03/2016 09:36 AM

☐ Critical Failure

Status Date: 12/16/2015 10:45 AM

#### 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Other Site Features

| Other Site i | eatures   |
|--------------|---|
| Page Last M  | odified: 06/02/2016   |
| Other Site   | Features  |
| 53.          | Pavement (Roadways and Parking Lots)                              |
|              | es es   |
| □ N          |   |
|              | 53a. Type: (check all that apply)                                 |
|              | □ Concrete  |
|              | <ul><li>☑ Asphalt</li><li>☐ Gravel</li></ul>                      |
|              | □ Other   |
|              | □ None  |
|              | 53b. Condition:   |
|              | □ Excellent   |
|              | ☑ Satisfactory  |
|              | <ul><li>☐ Unsatisfactory</li><li>☐ Non-Functioning</li></ul>      |
|              | ☐ Critical Failure  |
|              | 53c. Year of Last Major Reconstruction/Replacement:               |
|              | 2006  |
|              | 53d. Expected Remaining Useful Life (Years):                      |
|              |   |
|              | 52a Coot to Passanotyust/Paulosa (t.                              |
|              | 53e. Cost to Reconstruct/Replace \$:                              |
|              | 1,454,273.00  |
|              | 53f. Comments:  |
|              |   |
|              | Full depth reconstruction of East lot and mill south parking lot. |
| 54.          | Sidewalks   |
|              |   |
| ☑ Y<br>□ N   |   |
|              | 54a. Type: (check all that apply)                                 |
|              | ☑ Concrete  |
|              | ☑ Asphalt   |
|              | □ Paver □ Other   |
|              | 54b. Condition:   |
|              | Excellent   |
|              | ☐ Excellent ☐ Satisfactory  |
|              | □ Unsatisfactory  |
|              | □ Non-Functioning   |

06/03/2016 09:36 AM Page 12 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Other Site Features

| Page Last Modified: 06/02/2016  |
|---|
| 54c. Year of Last Major Reconstruction/Replacement:                           |
| 2008  |
| 54d. Expected Remaining Useful Life (Years):                                  |
| 4   |
| 54e. Cost to Reconstruct/Replace \$:  |
| 39,204.00   |
| 54f. Comments:  |
| Repair sidewalks on north side of school.                                     |
| 55. Playgrounds and Playground Equipment                                      |
| □ Yes   |
| ☑ No  |
| 56. Athletic Fields and Play Fields   |
| <ul><li>✓ Yes</li><li>□ No</li></ul>  |
| 56a. Condition:   |
| □ Excellent   |
| <ul><li>✓ Satisfactory</li><li>Unsatisfactory</li></ul>                       |
| □ Non-Functioning   |
| ☐ Critical Failure  |
| 56b. Year of Last Major Reconstruction/Replacement:                           |
| 2005  |
| 56c. Expected Remaining Useful Life (Years):                                  |
|   |
| 56d. Cost to Reconstruct/Replace \$:  |
| 100,460.00  |
| 56e. Comments:  |
|   |
| Improve drainage at upper soccer stadium, improve drainage at baseball field. |
| 56f. Does the facility have synthetic turf field(s)  □ Yes                    |
| □ No  |
| 56f.1 If Yes, how many synthetic turf fields?                                 |
| (No Response)   |

06/03/2016 09:36 AM Page 13 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Other Site Features

2,000.00

| Sition of the Front of the Fron |
|--|
| Page Last Modified: 06/02/2016   |
| 56f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):   |
| (No Response)  |
| 56f.3 Type of synthetic turf field infill:   |
| (No Response)  |
| 57. Exterior Bleachers / Stadiums  |
| <ul><li>✓ Yes</li><li>□ No</li></ul>   |
| 57a. Condition:  |
| <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>   |
| 57b. Year of Last Major Reconstruction/Replacement:  |
| 2005   |
| 57c. Expected Remaining Useful Life (Years):   |
| 5  |
| 57d. Cost to Reconstruct/Replace \$:   |
| (No Response)  |
| 57e. Comments:   |
| (No Response)  |
| 58. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)  |
| ☑ Yes  |
| □ No   |
| 58a. Condition:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure  |
| 58b. Year of Last Major Reconstruction/Replacement:  |
| 2000   |
| 58c. Expected Remaining Useful Life (Years):   |
| 4  |
| 58d. Cost to Reconstruct/Replace \$:   |

06/03/2016 09:36 AM Page 14 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Other Site Features

Page Last Modified: 06/02/2016

| FO-  | ^-  |    |    | 4   |
|------|-----|----|----|-----|
| 58e. | เ.ก | mm | en | TS: |

Corroded steel lintels in dugouts. Step cracks at southwest dugout.

06/03/2016 09:36 AM Page 15 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Substructure

| Page Last | Modified: 06/02/2016  |
|-----------|---|
| Substruc  | cture   |
| 59.       | . Foundation (S)  |
|           | 59a. Type (check all that apply):   |
|           | Reinforced Concrete  Masonry on Concrete Footing Other  |
|           | 59b. Evidence of structural concerns (check all that apply):  |
|           | <ul> <li>Structural Cracks</li> <li>Heaving/Jacking</li> <li>Decay/Corrosion</li> <li>Water Penetration</li> <li>Unsupported Ends</li> <li>Other</li> <li>✓ None</li> </ul> |
|           | 59c. Condition:   |
|           | <ul> <li>□ Excellent</li> <li>□ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>                                    |
|           | 59d. Year of Last Major Reconstruction/Replacement:   |
|           | 1966  |
|           | 59e. Expected Remaining Useful Life (Years):  |
|           | 35  |
|           | 59f. Cost to Reconstruct/Replace \$:  |
|           | (No Response)   |
|           | 59g. Comments:  |
|           | (No Response)   |

06/03/2016 09:36 AM Page 16 of 48

# Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

| Page | Last | Modifie   | d. 0 | 6/02 | 2/201 | 16 |
|------|------|-----------|------|------|-------|----|
| ıauc | Lasi | IVIOGILIC | u. u |      | _/    | ıv |

#### **BUILDING ENVELOPE**

| 60. | Structural Floors (S)  |
|-----|--|
|     | 60a. Type (check all that apply):  |
|     | Reinforced Concrete Slab on Grade Concrete/Metal Deck/Metal Joists Precast Concrete Structural System Wood Deck on Wood Trusses Wood Deck on Wood Joists Concrete Deck on Wood Structure Other (specify)           |
|     | 60b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):  |
|     | <ul> <li>□ Structural Cracks</li> <li>□ Unsupported Ends</li> <li>□ Rot/Decay/Corrosion</li> <li>□ Deflection</li> <li>□ Seriously Damaged/Missing Components</li> <li>□ Other Problems</li> <li>☑ None</li> </ul> |
|     | 60b.1 Describe Other Problems:   |
|     | (No Response)  |
|     | 60c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):  □ Cracks □ Deflection □ Rot/Decay/Corrosion □ None  |
|     | 60d. Overall Condition of Structural Floors:   |
|     | <ul> <li>□ Excellent</li> <li>□ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>   |
|     | 60e. Year of Last Major Reconstruction/Replacement:  |
|     | 1966   |
|     | 60f. Expected Remaining Useful Life (Years):   |
|     | 30   |
|     | 60g. Cost to Reconstruct/Replace \$:   |
|     | (No Response)  |
|     | 60h. Comments:   |
|     | Some C.I.P. concrete cracking and efflorescence at pool.   |

Page 17 of 48 06/03/2016 09:36 AM

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| building El                    | invelope   |  |
|--------------------------------|--|--|
| Page Last Modified: 06/02/2016 |  |  |
| 61.                            | Exterior Walls/Columns (S)   |  |
| _                              | 61a. Material (check all that apply):  |  |
|                                | Concrete   |  |
| <b>2</b>                       | Masonry Steel  |  |
|                                | Wood   |  |
|                                | Other (specify)  |  |
|                                | 61b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply): |  |
|                                | ✓ Structural Cracks  |  |
|                                | □ Rot/Decay/Corrosion  |  |
|                                | ☐ Other Problems ☐ None  |  |
|                                |  |  |
|                                | 61b.1 Describe Other Problems:   |  |
|                                | (No Response)  |  |
|                                | 61c. Evidence of Concerns with Exterior Cladding (check all that apply):   |  |
|                                | <ul> <li>☑ Cracks/Gaps</li> <li>☐ Inadequate Flashing</li> </ul>   |  |
|                                | □ Efflorescence  |  |
|                                | Moisture Penetration   |  |
|                                | □ Rot/Decay/Corrosion □ Other Problems   |  |
|                                | □ None   |  |
|                                | 61c.1 Describe Other Problems:   |  |
|                                | 2 lintels require replacement.   |  |
|                                | 61d. Overall Condition of Exterior Walls/Columns:  |  |
|                                | □ Excellent  |  |
|                                | ☑ Satisfactory   |  |
|                                | ☐ Unsatisfactory ☐ Non-Functioning   |  |
|                                | □ Critical Failure   |  |
|                                | 61e. Year of Last Major Reconstruction/Replacement:  |  |
|                                | 2006   |  |
|                                | 61f. Expected Remaining Useful Life (Years):   |  |
|                                | 25   |  |
|                                | 61g. Cost to Reconstruct/Replace \$:   |  |
|                                | 5,326.00   |  |
|                                | 61h. Comments:   |  |
|                                |  |  |

Page 18 of 48 06/03/2016 09:36 AM

Repoint various locations around building and cracks in brick veneer.

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

**Building Envelope** 

| Page Last Modified: 06/02/2016 |  |
|--------------------------------|--|
| <b>62</b> . □                  | Chimneys (S) Yes No  |
|                                | 62a. Material (check all that apply):  ✓ Masonry  Concrete  Metal  Wood  Other   |
|                                | 62a.1 Specify other:   |
|                                | (No Response)  |
|                                | 62b. Overall Condition of Chimneys:  |
|                                | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical failure</li> </ul> |
|                                | 62c. Year of Last Major Reconstruction/Replacement:  |
|                                | 2006   |
|                                | 62.d Expected Remaining Useful Life (Years):   |
|                                | 25   |
|                                | 62e. Cost to Reconstruct/Replace \$:   |
|                                | (No Response)  |
|                                | 62f. Comments:   |
|                                | (No Response)  |
| <b>63.</b> □                   | Parapets (S) Yes No  |
|                                | 63a. Construction Type (check all that apply):  ☑ Masonry  |
|                                | <ul><li>✓ Concrete</li><li>□ Metal</li><li>□ Wood</li></ul>  |
|                                | □ Other (specify)  |
|                                | 63a.1 Specify Other:   |
|                                | (No Response)  |

06/03/2016 09:36 AM Page 19 of 48

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| Building Envelope   |  |
|---|--|
| Page Last Modified: 06/02/2016  |  |
| 63b. Overall condition of parapets:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure               |  |
| 63c. Year of Last Major Reconstruction/Replacement:   |  |
| 63d. Expected Remaining Useful Life (Years):  |  |
| 63e. Cost to Reconstruct/Replace \$:  |  |
| (No Response)   |  |
| 63f. Comments:  |  |
| (No Response)   |  |
| 64. Exterior Doors  |  |
| 64a. Overall Condition of Exterior Door Units:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure    |  |
| 64b. Overall condition of exterior door hardware:  ☐ Excellent ☐ Satisfactory ☐ Unsatisfactory ☐ Non-Functioning ☐ Critical Failure |  |
| 64c. Do any exterior doors have magnetic locking devices?   |  |
| □ Yes □ No  |  |
| 64d. Safety/Security features are adequate?   |  |
| <ul><li>✓ Yes</li><li>□ No</li></ul>  |  |
| 64e. Year of Last Major Reconstruction/Replacement:   |  |
| 2000  |  |
| 64f. Expected Remaining Useful Life (Years):  |  |
| 10  |  |

Page 20 of 48 06/03/2016 09:36 AM

64g. Cost to Reconstruct/Replace \$:

10,000.00

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

**Building Envelope** 

| Page Last Modified: 06/02/2016   |  |
|--|--|
| 64h. Comments:   |  |
| Replace exterior frame, showing rusting and deterioration. Storefront needs reinforcing. |  |
| 65. Exterior Steps, Stairs, Ramps (S)  |  |
| ☑ No   |  |
| 66. Fire Escapes (S)   |  |
| 66a. Does This Facility Have One or More Fire Escapes?                                   |  |
| □ Yes ☑ No   |  |
|  |  |
| 67. Windows  |  |
|  |  |
| □ No   |  |
| 67a. Window Material: (check all that apply)   |  |
| <ul> <li>✓ Aluminum</li> <li>□ Steel</li> </ul>  |  |
| □ Vinyl  |  |
| □ Solid Wood □ Wood w/ External Cladding System  |  |
| ☐ Other  |  |
| 67b. Overall Condition of Windows:   |  |
| □ Excellent  |  |
| ☑ Satisfactory   |  |
| <ul><li>☐ Unsatisfactory</li><li>☐ Non-Functioning</li></ul>                             |  |
| □ Critical Failure   |  |
| 67c. All Rescue Windows are Operable:  |  |
|  |  |
| □ No □ N/A   |  |
| 67d. Year of Last Major Reconstruction/Replacement:                                      |  |
| 2000   |  |
|  |  |
| 67e. Expected Remaining Useful Life (Years):   |  |
| 15   |  |
| 67f. Cost to Reconstruct/Replace \$:   |  |
| (No Response)  |  |
| 67g. Comments:   |  |
| (No Response)  |  |

Roof and Skylights (S) 06/03/2016 09:36 AM Page 21 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page

| 9 2   |                    |
|---|--------------------|
| ast Modified: 06/02/2016  |                    |
| 68. Roof and Skylights (S)  |                    |
| ✓ Yes  □ No   |                    |
| 68a. Type of roof construction (check all that apply):  |                    |
| ✓ Metal deck on metal trusses/joists  |                    |
| □ Wood deck on wood trusses/joists  |                    |
| <ul> <li>□ Wood deck on metal trusses/joists</li> <li>□ Concrete on metal deck on metal trusses/joists</li> </ul> |                    |
| ☑ Other (describe below)  |                    |
| 68a.1 Other roof construction type:   |                    |
| Concrete plank  |                    |
| 68b. Type of roofing material (check all that apply):   |                    |
| ☑ Single-ply membrane   |                    |
| □ Built-up □ Asphalt shingle  |                    |
| ✓ Pre-formed metal  |                    |
| □ IRMA  |                    |
| □ Slate   |                    |
| ☐ Other (describe below)  |                    |
| 68b.1 Other roofing material:   |                    |
| (No Response)   |                    |
| 68c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (chec                  | k all that apply): |
| □ Structural cracks   |                    |
| <ul> <li>✓ Unsupported ends</li> <li>✓ Rot/Decay/Corrosion</li> </ul>   |                    |
| □ Deflection  |                    |
| □ Seriously damaged/missing components  |                    |
| ☐ Other concerns (describe)   |                    |
| □ None  |                    |
| 68c.1 Describe other concerns:  |                    |
| (No Response)   |                    |
| 68d. Evidence of structural concerns with roof deck (check all that apply):                                       |                    |
| ☑ Cracks  |                    |
| □ Deflection □ Ret/Descy/Comeries   |                    |
| <ul><li>☑ Rot/Decay/Corrosion</li><li>☐ None</li></ul>  |                    |
| 68e. Does this facility have skylights?   |                    |
| ✓ Yes   |                    |
| □ No.   |                    |

06/03/2016 09:36 AM Page 22 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Building Envelope

| Page Last Modified: 06/02/2016 |   |
|--------------------------------|---|
| 68f.                           | Skylight material (check all that apply):   |
|                                | Plastic Glass Other N/A   |
| 68g.                           | Overall condition of skylights:   |
|                                | Excellent Satisfactory  Unsatisfactory Non-Functioning Critical Failure   |
| 68h.                           | Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):   |
| I © (                          | Failures/Splits/Cracks Rot/Decay/Corrosion nadequate flashing/curbs/pitch pockets nadequate or poorly functioning roof drains Evidence of water penetration/active leaks Other (specify) None |
| 68h.                           | 1 Specify other concerns:   |
|                                | Response)   |
| 68i.                           | Overall Condition of Roof and Skylights:  |
| □ S<br>☑ U                     | Excellent Satisfactory Unsatisfactory Non-Functioning Critical Failure  |
| 68j.                           | Year of Last Major Reconstruction/Replacement:  |
| 2000                           |   |
| 68k.                           | Expected Remaining Useful Life (Years):   |
| 3                              |   |
| 681.                           | Cost to Reconstruct/Replace \$:   |
|                                | Response)   |
|                                | . Comments:   |
| Portio                         | ons of existing roof replaced   |

06/03/2016 09:36 AM Page 23 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| Interior Spaces   |   |
|---|---|
| Page Last Modified: 06/02/2016                                    |   |
| INTERIOR SPACES   |   |
| 69. Interior Bearing Walls and Fire Walls (S)                     |   |
| <ul><li>✓ Yes</li><li>□ No</li></ul>                              |   |
| 69a. Overall condition of interior bearing walls and fire walls:  |   |
| □ Excellent   |   |
| ☑ Satisfactory  |   |
| ☐ Unsatisfactory  |   |
| <ul> <li>□ Non-functioning</li> <li>□ Critical Failure</li> </ul> |   |
| 69b. Year of Last Major Reconstruction/Replacement:               |   |
| 2000  |   |
| 69c. Expected Remaining Useful Life (Years):                      |   |
| 20  |   |
| 69d. Cost to Reconstruct/Replace \$:                              |   |
| (No Response)   |   |
| 69e. Comments:  |   |
| (No Response)   |   |
| Other Interior Walls  | Π |
| 70. Other Interior Walls  |   |
| <ul><li>✓ Yes</li><li>□ No</li></ul>                              |   |
| 70a. Overall condition of other interior walls:                   |   |
| □ Excellent   |   |
| ☑ Satisfactory  |   |
| ☐ Unsatisfactory  |   |
| <ul> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul> |   |
| 70b. Year of Last Major Reconstruction/Replacement:               | Π |
| 2008  |   |
| 70c. Expected Remaining Useful Life (Years):                      |   |
| 13  |   |
| 70d. Cost to Reconstruct/Replace \$:                              |   |
| (No Response)   |   |
| 70e. Comments:  |   |
| (No Response)   |   |

**Floor Finishes** 

06/03/2016 09:36 AM Page 24 of 48

#### 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| Interior Spaces  |  |  |
|--|--|--|
| Page Last Modified: 06/02/2016   |  |  |
| 71. Carpet   |  |  |
| ✓ Yes  □ No  |  |  |
| 71a. Where located (check all that apply):   |  |  |
| <ul> <li>✓ Instructional Space</li> <li>Common Area</li> </ul>   |  |  |
| 71b. Condition:  |  |  |
| <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul> |  |  |
| 71c. Year of Last Major Reconstruction/Replacement:  |  |  |
| 2008   |  |  |
| 71d. Expected Remaining Useful Life (Years):   |  |  |
| 74a. Coat to Paganetruot/Paniago \$1   |  |  |
| 71e. Cost to Reconstruct/Replace \$:   |  |  |
| (No Response) 71f. Comments:   |  |  |
| 711. Comments.   |  |  |
| 72. Resilient Tiles or Sheet Flooring  |  |  |
| ✓ Yes  □ No  |  |  |
| 72a. Where located (check all that apply):   |  |  |
| <ul><li>✓ Instructional Space</li><li>Common Area</li></ul>  |  |  |
| 72b. Overall condition of resilient tiles or sheet flooring:   |  |  |
| <ul> <li>☑ Excellent</li> <li>☐ Satisfactory</li> <li>☐ Unsatisfactory</li> <li>☐ Non-Functioning</li> <li>☐ Critical Failure</li> </ul> |  |  |
| 72c. Year of Last Major Reconstruction/Replacement:  |  |  |
|  |  |  |

Page 25 of 48 06/03/2016 09:36 AM

72d. Expected Remaining Useful Life (Years):

10

#### **BROCKPORT CSD**

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Interior Spaces

| Page Last Modified: 06/02/2016  |
|---|
| 72e. Cost to Reconstruct/Replace \$:  |
| 37,721.00   |
| 72f. Comments:  |
|   |
| Replace damaged VCT tile in rooms 26, storage (ground floor), AUD, 181 and 190.   |
| 73. Hard Flooring (concrete; ceramic tile; stone; etc)  |
| ✓ Yes   |
| □ No  |
| 73a. Where located (check all that apply):  |
| <ul> <li>☐ Instructional Space</li> <li>☑ Common Area</li> </ul>  |
| 73b. Overall condition of hard flooring:  |
| Excellent   |
| <ul><li>✓ Satisfactory</li><li>Unsatisfactory</li></ul>   |
| □ Non-Functioning   |
| ☐ Critical Failure  |
| 73c. Year of Last Major Reconstruction/Replacement:   |
| 2000  |
| 73d. Expected Remaining Useful Life (Years):  |
| 20  |
| 73e. Cost to Reconstruct/Replace \$:  |
| 34,000.00   |
| 73f. Comments:  |
|   |
| Replace areas of damaged terrazzo tile. Rooms 18B, 1st floor hall, lobby, stair, 112B and 112G. Repaint concrete floor in rooms 20B, 132 and 135. |
| 74. Wood Flooring   |
| ✓ Yes  □ No   |
| 74a. Where located (check all that apply):  |
| ☐ Instructional Space   |
| ✓ Common Area   |
| 74b. Overall condition of wood flooring:  |
| <ul><li>□ Excellent</li><li>☑ Satisfactory</li></ul>  |
| <ul><li>□ Unsatisfactory</li><li>□ Non-Functioning</li></ul>  |
| <ul> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>   |

06/03/2016 09:36 AM Page 26 of 48

☐ Critical Failure

# Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

|          | nor opuses   |
|----------|--|
| Pag      | ge Last Modified: 06/02/2016   |
|          | 74c. Year of Last Major Reconstruction/Replacement:  |
|          | 2008   |
|          | 74d. Expected Remaining Useful Life (Years):   |
|          | 18   |
|          | 74e. Cost to Reconstruct/Replace \$:   |
|          | (No Response)  |
|          | 74f. Comments:   |
|          | (No Response)  |
| Ceilings | s (H)  |
|          | 5. Ceilings (H)  |
|          |  |
|          | 75a. Overall condition of ceilings:  |
|          | □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure                                       |
|          | 75b. Year of Last Major Reconstruction/Replacement:  |
|          | 2008   |
|          | 75c. Expected Remaining Useful Life (Years):   |
|          | 10   |
|          | 75d. Cost to Reconstruct/Replace \$:   |
|          | 3,200.00   |
|          | 75e. Comments:   |
|          | Replace various ceiling tile in rooms 106, SAP office, 10, 104 116, 131A, 146G, and 190). Repaint ceiling in room 132. |
| Lockers  |  |
| 76       |  |
| <b>∑</b> | Yes<br>No  |
|          | 76a. Overall condition of lockers:   |
|          | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> </ul>           |

Page 27 of 48 06/03/2016 09:36 AM

#### **BROCKPORT CSD**

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Interior Spaces

□ No

| Page Last Modified: 06/02/2016  |
|---|
| 76b. Year of Last Major Reconstruction/Replacement:                     |
| 2006  |
| 76c. Expected Remaining Useful Life (Years):                            |
| 20  |
| 76d. Cost to Reconstruct/Replace \$:                                    |
| 13,500.00   |
| 76e. Comments:  |
|   |
| Replace damaged lockers in girls' locker room.                          |
| Interior Doors  |
| 77. Interior Doors  |
| <ul><li>✓ Yes</li><li>□ No</li></ul>                                    |
| 77a. Overall condition of interior door units:                          |
| □ Excellent   |
| <ul><li>☑ Satisfactory</li><li>☐ Unsatisfactory</li></ul>               |
| □ Non-Functioning   |
| ☐ Critical Failure  |
| 77b. Overall condition of interior door hardware:                       |
| Excellent   |
| <ul><li>☑ Satisfactory</li><li>☐ Unsatisfactory</li></ul>               |
| □ Non-Functioning   |
| □ Critical Failure  77c. Year of Last Major Reconstruction/Replacement: |
| 1996  |
|   |
| 77d. Expected Remaining Useful Life (Years):                            |
| 77e. Cost to Reconstruct/Replace \$:                                    |
| 183,475.00  |
| 77f. Comments:  |
|   |
| Replace damaged doors.  |
| Interior Stairs (S)   |
| 78. Interior Stairs (S)   |
| ✓ Yes   |

06/03/2016 09:36 AM Page 28 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

| Page Last Modified: 06/02/2  | 2016                                   |
|--|--|
| 78a. Overall o   | condition of interior stairs:          |
| <ul> <li>□ Excellent</li> <li>□ Satisfactory</li> <li>□ Unsatisfactor</li> <li>□ Non-Function</li> <li>□ Critical Failu</li> </ul> | ning                                   |
| 78b. Year of L   | _ast Major Reconstruction/Replacement: |
| 1966   |  |
| 78c. Expected  | d Remaining Useful Life (Years):       |
| 25   |  |
| 78d. Cost to F   | Reconstruct/Replace \$:                |
| (No Response)  |  |
| 78e. Commen  | its:                                   |
| (No Response)  |  |
| Elevator, Lifts and Escal  |  |
| 79. Elevator, Lift, a  ✓ Yes  □ No   | nd Escalators (H)                      |
| 79a. Overall o  □ Excellent □ Satisfactory □ Unsatisfactor □ Non-Function □ Critical Failur  | ning                                   |
| 79b. Year of L   | ast Major Reconstruction/Replacement:  |
| 1992   |  |
| 79c. Expected  | d Remaining Useful Life (Years):       |
| 7  |  |
| 79d. Cost to F   | Reconstruct/Replace \$                 |
| (No Response)  |  |
| 79e. Commen  | its:                                   |
| (No Response)  |  |
| Interior Electrical Distrib  | ution (H)                              |
| 80. Interior Electric  | al Distribution (H)                    |
| ✓ Yes  |  |

06/03/2016 09:36 AM Page 29 of 48

# Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

| Page Last M                          | Modified: 06/02/2016  |
|--------------------------------------|---|
| 80a.                                 | Interior electrical supply meets current needs:   |
|                                      |   |
|                                      | Condition of interior electrical distribution:  |
| ☑ S                                  | Jnsatisfactory  |
|                                      | Non-Functioning Critical Failure  |
| 80c.                                 | Year of Last Major Reconstruction/Replacement:  |
| 2008                                 |   |
| 80d.                                 | Expected Remaining Useful Life (Years):   |
| 25                                   |   |
| 80e.                                 | Cost to Reconstruct/Replace \$:   |
| (No B                                | Response)   |
| 80f.                                 | Comments:   |
|                                      |   |
| Altho                                | ugh main power distribution components are newer, some of the local branch circuit panels were installed in 2000. |
| Lighting Fixture                     | s   |
| 81. Interio                          | or Lighting Fixtures  |
| <ul><li>✓ Yes</li><li>□ No</li></ul> |   |
| 81a.                                 | Condition of interior lighting fixtures:  |
| _                                    | Excellent<br>Satisfactory   |
|                                      | Insatisfactory  |
|                                      | Non-Functioning Critical Failure  |
|                                      | Year of Last Major Reconstruction/Replacement:  |
| 2000                                 |   |
| 81c.                                 | Expected Remaining Useful Life (Years):   |
| 10                                   |   |
| 81d.                                 | Cost to Reconstruct/Replace \$:   |
| (No F                                | Response)   |
| 81e.                                 | Comments:   |
| (No F                                | Response)   |
| Communication                        | Systems (H)   |

Page 30 of 48 06/03/2016 09:36 AM

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| Interior Spaces |  |  |
|-----------------|--|--|
|                 |  |  |

| Page Last Modified: 06/02/2016 |  |
|--------------------------------|--|
| 82.                            | Communication Systems (H)                                    |
| <b>S</b>                       | Yes<br>No  |
|                                | 82a. Communication systems are adequate:                     |
|                                | ✓ Yes  |
|                                | □ No   |
|                                | 82b. Condition of communication systems:                     |
|                                | <ul><li>□ Excellent</li><li>□ Satisfactory</li></ul>         |
|                                | □ Unsatisfactory   |
|                                | □ Non-Functioning □ Critical Failure                         |
|                                | 82c. Year of Last Major Reconstruction/Replacement:          |
|                                | 2000   |
|                                | 82d. Expected Remaining Useful Life (Years):                 |
|                                | 15   |
|                                | 82e. Cost to Replace/Reconstruct \$:                         |
|                                | (No Response)  |
|                                | 82f. Comments:   |
|                                | (No Response)  |
| Swimmin                        | g Pool and Swimming Pool Systems                             |
| 83.                            | Swimming Pool and Swimming Pool Systems                      |
|                                | Yes<br>No  |
|                                | 83a. Overall condition of swimming pool and pool systems:    |
|                                | Excellent  |
|                                | ☑ Satisfactory   |
|                                | <ul><li>□ Unsatisfactory</li><li>□ Non-Functioning</li></ul> |
|                                | □ Critical Failure   |
|                                | 83b. Year of Last Major Reconstruction/Replacement:          |
|                                | 1970   |
|                                | 83c. Expected Remaining Useful Life (Years):                 |
|                                | 30   |
|                                | 83d. Cost to Reconstruct/Replace \$:                         |
|                                | (No Response)  |
|                                | 83e. Comments:   |
|                                | Tile needs replacement or regrouting in the next few years.  |

06/03/2016 09:36 AM Page 31 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Satisfactory ☐ Unsatisfactory ☐ Non-Functioning ☐ Critical Failure

| Plumbing (Excluding HVAC Systems)                       |
|---|
| Page Last Modified: 06/02/2016                          |
| PLUMBING  |
| 84. Water Distribution System (H)                       |
| <ul><li>✓ Yes</li><li>□ No</li></ul>                    |
| 84a. Types of pipes (check all that apply):             |
| □ Iron  |
| ✓ Galvanized  |
| <ul><li>✓ Copper</li><li>□ Lead</li></ul>               |
| □ PVC   |
| □ Other   |
| 84b. Overall condition of water distribution system:    |
| □ Excellent   |
| <ul><li>✓ Satisfactory</li><li>Unsatisfactory</li></ul> |
| ☐ Unsatisfactory ☐ Non-Functioning                      |
| ☐ Critical Failure                                      |
| 84c. Year of Last Major Reconstruction/Replacement:     |
| 2000  |
| 84d. Expected Remaining Useful Life (Years):            |
| 10  |
| 84e. Cost to Reconstruct/Replace \$:                    |
| (No Response)   |
| 84f. Comments:  |
| (No Response)   |
| Plumbing Drainage System (H)                            |
| 85. Plumbing Drainage System (H)                        |
| <ul><li>✓ Yes</li><li>□ No</li></ul>                    |
| 85a. Types of pipes (check all that apply):             |
| ☑ Iron  |
| ☑ Galvanized  |
| ☐ Copper ☐ Lead   |
| □ PVC   |
| □ Other   |
| 85b. Overall condition of drainage system:              |
| ☐ Excellent   |

Page 32 of 48 06/03/2016 09:36 AM

# Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Plumbing (Excluding HVAC Systems)

| Pa      | e Last Modified: 06/02/2016  |  |
|---------|--|--|
|         | 85c. Year of Last Major Reconstruction/Replacement:                            |  |
|         | 2000   |  |
|         | 85d. Expected Remaining Useful Life (Years):                                   |  |
|         | 10   |  |
|         | 85e. Cost to Reconstruct/Replace \$:   |  |
|         | (No Response)  |  |
|         | 85f. Comments:   |  |
|         |  |  |
|         | Repair/seal floor around floor drains toilet rooms, 216B, 216G, 112B and 112G. |  |
| Hot Wat | r Heaters (H)  |  |
| 80      | Hot Water Heaters (H)  |  |
|         | Yes<br>No  |  |
| _       | 86a. Type of fuel (check all that apply):                                      |  |
|         | Oil  |  |
|         | ☑ Natural Gas  |  |
|         | □ Electricity □ Propane  |  |
|         | Other  |  |
|         | 86b. Overall condition of hot water heaters:                                   |  |
|         | □ Excellent  |  |
|         | <ul><li>✓ Satisfactory</li><li>Unsatisfactory</li></ul>                        |  |
|         | □ Non-Functioning  |  |
|         | □ Critical Failure   |  |
|         | 86c. Year of Last Major Reconstruction/Replacement:                            |  |
|         | 2000   |  |
|         | 86d. Expected Remaining Useful Life (Years):                                   |  |
|         | 10   |  |
|         | 86e. Cost to Reconstruct/Replace \$:   |  |
|         | (No Response)  |  |
|         | 86f. Comments:   |  |
|         | (No Response)  |  |
|         | y Fixtures   |  |
|         | Plumbing Fixtures  |  |
|         | Yes<br>No  |  |
|         |  |  |

Page 33 of 48 06/03/2016 09:36 AM

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Plumbing (Excluding HVAC Systems)

Page Last Modified: 06/02/2016

| 87a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, etc): |  |  |
|--|--|--|
| □ Excellent  |  |  |
| ✓ Satisfactory   |  |  |
| □ Unsatisfactory   |  |  |
| □ Non-Functioning  |  |  |
| □ Critical Failure   |  |  |
| 87b. Year of Last Major Reconstruction/Replacement:  |  |  |
| 2005   |  |  |
| 87c. Expected Remaining Useful Life (Years):   |  |  |
| 5  |  |  |
| 87d. Cost to Reconstruct/Replace \$:   |  |  |
| (No Response)  |  |  |
| 87e. Comments:   |  |  |
| (No Response)  |  |  |

06/03/2016 09:36 AM Page 34 of 48

#### 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

**HVAC Systems** Page Last Modified: 06/02/2016 **HVAC SYSTEMS** 88. HVAC Systems Type 88a. Does this building have a central HVAC system? ~ No **Heat Generating Systems (H)** 88b.1 Other central HVAC system technology: (No Response) 89. Heat Generating Systems (H) □ No 89a. Heat generation source (check all that apply): ☑ Boiler / Hot Water □ Boiler / Steam ☐ Furnace / Forced Air ☑ Unit Ventilation ☐ Geothermal □ Biomass □ Electric ☑ Other (describe below) 89a.1 Other heat generation source: CEO Heat Pumps. 89b. Overall condition of heat generating systems: ☐ Excellent ☑ Satisfactory □ Unsatisfactory □ Non-Functioning ☐ Critical Failure 89c. Year of Last Major Reconstruction/Replacement:

Toda of East major Reconstruction/Replacement

2000

89d. Expected Remaining Useful Life (Years):

5

89e. Cost to Reconstruct/Replace \$:

(No Response)

89f. Comments:

Piping was reworked in 2015 to the boilers.

**Heating Fuel/Energy Systems (H)** 

06/03/2016 09:36 AM Page 35 of 48

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| HVAC Syste                        | ems  |
|-----------------------------------|--|
| Page Last M                       | Modified: 06/02/2016   |
| 90.                               | Heating Fuel / Energy Systems (H)  |
| <ul><li>✓ Y</li><li>□ N</li></ul> | Yes<br>No  |
|                                   | 90a. Overall condition of heating fuel / energy systems:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure |
|                                   | 90b. Year of Last Major Reconstruction/Replacement:  |
|                                   | 2000   |
|                                   | 90c. Expected Remaining Useful Life (Years):   |
|                                   | 90d. Cost to Reconstruct/Replace \$:   |
|                                   | (No Response)  |
|                                   | 90e. Comments:   |
|                                   | (No Response)  |
| Cooling/Ai                        | ir Conditioning Generating Systems   |
| 91.                               | Cooling / Air-Conditioning Generating Systems  |
| <ul><li>☑ Y</li><li>□ N</li></ul> | Yes<br>No  |
|                                   | 91a. Overall condition of cooling/air-conditioning generating systems:   |
|                                   | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>   |
|                                   | 91b. Year of Last Major Reconstruction/Replacement:  |
|                                   | 2000   |
|                                   | 91c. Expected Remaining Useful Life (Years):   |
|                                   | 5  |

AIR HANDLING AND VENTILATION EQUIPMENT

(No Response)

(No Response)

91e. Comments:

91d. Cost to Reconstruct/Replace \$:

06/03/2016 09:36 AM Page 36 of 48

### 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| HVAC Systems |  |
|--------------|--|
|--------------|--|

| HVAC Systems  |
|---|
| Page Last Modified: 06/02/2016  |
| 92. Air Handling and Ventilation Equipment: Supply Units, Exhaust Units, Relief/Return Units, etc. (H)  |
| ✓ Yes  □ No   |
| 92a. Overall condition of air handling and ventilation systems:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure |
| 92b. Year of Last Major Reconstruction/Replacement:   |
| 2000  |
| 92c. Expected Remaining Useful Life (Years):  |
| 5   |
| 92d. Cost to Reconstruct/Replace \$:  |
| (No Response)   |
| 92e. Comments:  |
| (No Response)   |
| Piped Heating and Cooling Distribution Systems  |
| 93. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectorss, Traps, Insulation, etc. (H)                            |
| <ul><li>✓ Yes</li><li>□ No</li></ul>  |
| 93a. Overall condition of piped heating and cooling distribution systems:   |
| <ul> <li>□ Excellent</li> <li>□ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>          |
| 93b. Year of Last Major Reconstruction/Replacement:   |
| 2000  |
| 93c. Expected Remaining Useful Life (Years):  |

**Ducted Heating and Cooling Distrbution Systems** 

2015 valve replacement-partial.

93d. Cost to Reconstruct/Replace \$:

15

(No Response)

93e. Comments:

Page 37 of 48 06/03/2016 09:36 AM

## Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

HVAC Systems

| Page | Last | Modifie   | d. 0 | 6/02 | 2/201 | 16 |
|------|------|-----------|------|------|-------|----|
| ıauc | Lasi | IVIOGILIC | u. u |      | _/    | ıv |

|     | loo   |
|-----|---|
|     | Ves<br>No   |
|     | 94a. Overall condition of ducted heating and cooling distribution systems:  |
|     | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>  |
|     | 94b. Year of Last Major Reconstruction/Replacement:   |
|     | 2000  |
|     | 94c. Expected Remaining Useful Life (Years):  |
|     | 15  |
|     | 94d. Cost to Reconstruct/Replace \$:  |
|     | (No Response)   |
|     | 94e. Comments:  |
|     | (No Response)   |
| Con | atrol Systems   |
| 95. | HVAC Control Systems (H)  |
| ✓ Y |   |
|     | Ves<br>No   |
| □ N | No  |
| □ N |   |
| □ N | 95a. Overall condition of control systems:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning   |
|     | 95a. Overall condition of control systems:  Excellent  Satisfactory  Unsatisfactory  Non-Functioning  Critical Failure  |
|     | 95a. Overall condition of control systems:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure  95b. Year of Last Major Reconstruction/Replacement:   |
|     | 95a. Overall condition of control systems:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure  95b. Year of Last Major Reconstruction/Replacement:   |
| □ N | 95a. Overall condition of control systems:  □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure  95b. Year of Last Major Reconstruction/Replacement:  2000  95c. Expected Remaining Useful Life (Years): |
| □ N | 95a. Overall condition of control systems:    Excellent   Satisfactory   Unsatisfactory   Non-Functioning   Critical Failure  95b. Year of Last Major Reconstruction/Replacement: 2000  95c. Expected Remaining Useful Life (Years):  |

Page 38 of 48 06/03/2016 09:36 AM

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| Fire S | Safety | Systems |  |
|--------|--------|---------|--|
|--------|--------|---------|--|

| Page Last Modified: 06/02/2016   |
|--|
| Fire Safety Systems  |
| 96. Fire Alarm Systems (H)   |
| <ul><li>✓ Yes</li><li>□ No</li></ul>   |
| 96a. Overall condition of fire alarm system:                                     |
| □ Excellent  |
| <ul><li>✓ Satisfactory</li><li>Unsatisfactory</li></ul>                          |
| □ Non-Functioning □ Critical Failure   |
| 96b. Year of Last Major Reconstruction/Replacement:                              |
| 2000   |
| 96c. Expected Remaining Useful Life (Years):                                     |
| 15   |
| 96d. Cost to Reconstruct/Replace \$:   |
| 30,000.00  |
| 96e. Comments:   |
|  |
| Current SED standards require stobes in all classromms, approximately 100 rooms. |
| Smoke Detection System (H)   |
| 97. Smoke Detection Systems (H)  ✓ Yes   |
| □ No   |
| 97a. Overall condition of smoke detection systems:                               |
| <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> </ul>                          |
| □ Unsatisfactory   |
| <ul> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>                |
| 97b. Year of Last Major Reconstruction/Replacement:                              |
| 2000   |
| 97c. Expected Remaining Useful Life (Years):                                     |
| 5  |
| 97d. Cost to Reconstruct/Replace \$:   |
| 60,000,00  |

06/03/2016 09:36 AM Page 39 of 48

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

|      | Fire Sa | fety Systems  |
|------|---------|---|
| -    | Page L  | ast Modified: 06/02/2016  |
|      |         | 97e. Comments:  |
|      |         |   |
|      |         | Manufacturers typically recommend replacement every 15 years of smoke/heat sensing elements. Current SED standards require smoke detection in all classrooms. |
| Fire | Suppre  | ession Systems  |
| •    |         | Fire Suppression Systems: Sprinklers, Standpipes, Kitchen Hoods, etc. (H)   |
|      | ☑ Ye    | s   |
|      |         | 98a. Overall condition of fire suppression systems:   |
|      |         | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>                      |
|      |         | 98b. Year of Last Major Reconstruction/Replacement:   |
|      |         | 2000  |
|      |         | 98c. Expected Remaining Useful Life (Years):  |
|      |         | 5   |
|      |         | 98d. Cost to Reconstruct/Replace \$:  |
|      |         | (No Response)   |
|      |         | 98e. Comments:  |
|      |         | (No Response)   |
| Eme  | rgency  | /Exit Lighting Systems  |
|      | 99. I   | Emergency / Exit Lighting Systems (H)   |
|      | ☑ Ye    |   |
|      |         | 99a. Overall condition of emergency / exit lighting systems:  |
|      |         | <ul> <li>□ Excellent</li> <li>☑ Satisfactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Critical Failure</li> </ul>                      |
|      |         | 99b. Year of Last Major Reconstruction/Replacement:   |
|      |         | 2000  |

06/03/2016 09:36 AM Page 40 of 48

99c. Expected Remaining Useful Life (Years):

99d. Cost to Reconstruct/Replace \$:

30,000.00

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Fire Safety Systems

| Page L                               | ast Modified: 06/02/2016  |
|--------------------------------------|---|
|                                      | 99e. Comments;  |
|                                      |   |
|                                      | Emergency lighting system should include all exit discharge spaces, approximately 22 areas.   |
| Emergency/                           | Standby Power Systems   |
| 100.                                 | Emergency or Standby Power System (H)   |
| <ul><li>✓ Yes</li><li>□ No</li></ul> |   |
|                                      | 100a. Overall condition of emergency/standby power systems:   |
|                                      | <ul> <li>□ Excellent</li> <li>□ Satifactory</li> <li>□ Unsatisfactory</li> <li>□ Non-Functioning</li> <li>□ Crtitical Failure</li> <li>□ N/A</li> </ul> |
|                                      | 100b. Year of Last Major Reconstruction/Replacement:  |
|                                      | 2008  |
|                                      | 100c. Expected Remaining Useful Life (Years):   |
|                                      | 18.00   |
|                                      | 100d. Cost to Reconstruct/Replace \$:   |
|                                      | (No Response)   |
|                                      | 100e. Comments:   |
|                                      | (No Response)   |

Page 41 of 48 06/03/2016 09:36 AM

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Accessibility

Page Last Modified: 03/16/2016

#### **ACCESSIBILITY**

101. Exterior Accessible Route (H)

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

| enter the building.  |
|--|
| Is there an accessible exterior route as specified above?  |
| ☑ Yes<br>□ No  |
| 102. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)  |
| The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities. |
| Is there an accessible interior route as specified above?  |
| ☑ Yes<br>□ No  |
| 103. Additional Information on Accessibility   |
| If the building lacks accessible interior or exterior routes:  |
| 103a. Cost of improvements needed to provide accessible exterior and interior routes as specified above \$:  |
| (No Response)  |
| 103b. Comments:  |
|  |
| (No Response)  |

06/03/2016 09:36 AM Page 42 of 48

### 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Environment/Comfort/Health

| Page | Last | Modified: | 03/16/201 | 6 |
|------|------|-----------|-----------|---|
| ıauc | ∟ası | MOUILIEU. | 03/10/201 | v |

|           | /ID                                     | ~       |              |         |       | _    |           |     |    |       |
|-----------|---|---------|--------------|---------|-------|------|-----------|-----|----|-------|
| $-\kappa$ | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | ת ואר ז | $M \vdash P$ | IT/C    | r ana | L( ) | <b>טו</b> | нь/ | ۱ı | - 1 — |
| -14       | , ,,,                                   | CIVI    | 41 L I'      | 4 I / C |       |      | IN I/     |     | ٦L | _     |

| RONMENT/COMFORT/HEALTH  |
|---|
| 104. General Appearance   |
| 104a. Overall Rating:   |
| ☑ Good<br>□ Fair  |
| □ Poor  |
| 104b. Comments:   |
| (No Response)   |
| 105. Cleanliness  |
| 105a. Overall Rating:   |
| ☑ Good □ Fair □ Poor  |
| 105b. Comments:   |
|   |
| (No Response)   |
| 106. Are there walk off mats; grills in the entryway?                                       |
| <ul><li>✓ Yes</li><li>□ No</li></ul>  |
| 106a. If yes: at least 6 feet long?   |
| <ul><li>✓ Yes</li><li>□ No</li></ul>  |
| 107. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? |
| □ Yes   |
| ☑ No  |
| 108. Lighting Quality:  |
| 108a. Types of lighting in general purpose classrooms (check all that apply):               |
| ✓ Daylight  |
| ☐ Flourescent-not full spectrum   |
| Flourescent full spectrum   |

108b. Are there blinds in the classroom to prevent glare?

□ Fair □ Poor

| <b>Y</b> | ✓ Yes                 |  |
|----------|-----------------------|--|
|          | □ No                  |  |
| 108      | 108c. Overall Rating: |  |
|          |                       |  |

Page 43 of 48 06/03/2016 09:36 AM

**BROCKPORT CSD** 

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Environment/Comfort/Health

| Pag                     | e Last Modified: 03/16/2016  |  |  |  |  |  |  |  |
|-------------------------|--|--|--|--|--|--|--|--|
|                         | 108d. Comments:  |  |  |  |  |  |  |  |
|                         | (No Response)  |  |  |  |  |  |  |  |
| 109. Evidence of Vermin |  |  |  |  |  |  |  |  |
|                         | 109a. Is there evidence of active infestations of(check all that apply)? |  |  |  |  |  |  |  |
|                         | Rodents  |  |  |  |  |  |  |  |
|                         | Wood-boring or Wood-eating Insects                                       |  |  |  |  |  |  |  |
|                         | Cockroaches  |  |  |  |  |  |  |  |
|                         | Other Vermin   |  |  |  |  |  |  |  |
| $\overline{\mathbf{z}}$ | None   |  |  |  |  |  |  |  |

06/03/2016 09:36 AM Page 44 of 48

#### **PORT CSD** Status Date: 12/16/2015 10:45 AM

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

| ndoor Air Quality   |  |  |  |  |  |  |  |
|---|--|--|--|--|--|--|--|
| Page Last Modified: 03/16/2016  |  |  |  |  |  |  |  |
| Indoor Air Quality  |  |  |  |  |  |  |  |
| 110. Mold   |  |  |  |  |  |  |  |
| 110a. Is there visible mold or moldy odors?   |  |  |  |  |  |  |  |
| □ Yes ☑ No  |  |  |  |  |  |  |  |
| <ul> <li>110c. Are any surfaces constructed of any of the following materials?</li> <li>☑ Paper-faced or gypsum products</li> <li>☑ Cellulose products (typically ceiling tiles)</li> </ul> |  |  |  |  |  |  |  |
| 110d. Estimated cost of necessary improvements \$:  |  |  |  |  |  |  |  |
| (No Response)   |  |  |  |  |  |  |  |
| 110d. Comments:   |  |  |  |  |  |  |  |
| (No Response)   |  |  |  |  |  |  |  |
| 111. Humidity/Moisture  |  |  |  |  |  |  |  |
| 111a. Overall rating of humidity/moisture condition in building:  |  |  |  |  |  |  |  |
| □ Good ☑ Fair □ Poor  111b. Are any of the following found in/or around classroom areas (check all that apply)?   |  |  |  |  |  |  |  |
| Active leaks in roof  |  |  |  |  |  |  |  |
| <ul> <li>□ Active leaks in plumbing</li> <li>□ Moisture condensation</li> <li>□ Visible stains or water damage</li> </ul>   |  |  |  |  |  |  |  |
| ✓ None  |  |  |  |  |  |  |  |
| 111c. Are any of the following found in/or around other areas (check all that apply)?   |  |  |  |  |  |  |  |
| <ul> <li>□ Active leaks in roof</li> <li>□ Active leaks in plumbing</li> <li>□ Moisture condensation</li> </ul>   |  |  |  |  |  |  |  |
| <ul><li>□ Visible stains or water damage</li><li>☑ None</li></ul>   |  |  |  |  |  |  |  |
| 112. Ventilation: fresh air intake locations, air filters, etc.   |  |  |  |  |  |  |  |
| 112a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?  |  |  |  |  |  |  |  |
| □ Yes ☑ No  |  |  |  |  |  |  |  |
| 112b. Is there accumulated dirt, dust or debris around fresh air intakes?   |  |  |  |  |  |  |  |
| □ Yes ☑ No  |  |  |  |  |  |  |  |
| 112c. Are fresh air intakes free of blockage?   |  |  |  |  |  |  |  |
| <ul><li>✓ Yes</li><li>□ No</li></ul>  |  |  |  |  |  |  |  |

06/03/2016 09:36 AM Page 45 of 48

## Status Date: 12/16/2015 10:45 AM 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Indoor Air Quality

Page Last Modified: 03/16/2016

| 112d. Is accumulated dirt, dust or debris in ductwork?   |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
| Yes  |  |  |  |  |  |  |
| ☑ No   |  |  |  |  |  |  |
| 112e. Are dampers functioning as designed?   |  |  |  |  |  |  |
| ✓ Yes  □ No  |  |  |  |  |  |  |
| 112f. Condition of air filters:  |  |  |  |  |  |  |
| ☑ Good   |  |  |  |  |  |  |
| □ Fair □ Poor  |  |  |  |  |  |  |
| 112g. Outside air is adequate for occupant load:   |  |  |  |  |  |  |
| ☑ Yes  |  |  |  |  |  |  |
| □ No  112h. Rating of ventilation/indoor air quality:  |  |  |  |  |  |  |
| ✓ Good   |  |  |  |  |  |  |
| □ Fair   |  |  |  |  |  |  |
| □ Poor   |  |  |  |  |  |  |
| 112i. Comments:  |  |  |  |  |  |  |
| (No Response)  |  |  |  |  |  |  |
| 113. Indoor Air Quality (IAQ) Plan   |  |  |  |  |  |  |
| 113a. Does the school district use EPA's Tools for Schools program?  |  |  |  |  |  |  |
| ✓ Yes  |  |  |  |  |  |  |
| □ No   |  |  |  |  |  |  |
| 113c. Has the District assigned IAQ responsibilities to a designated individual?   |  |  |  |  |  |  |
|  |  |  |  |  |  |  |
| ✓ Yes  □ No  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |
| ✓ Yes □ No   |  |  |  |  |  |  |
| ✓ Yes  □ No  113c.1 If Yes, what is their job title?   |  |  |  |  |  |  |
| <ul> <li>✓ Yes</li> <li>☐ No</li> <li>113c.1 If Yes, what is their job title?</li> <li>Director of building grounds.</li> </ul>  |  |  |  |  |  |  |
| <ul> <li>✓ Yes</li> <li>No</li> <li>113c.1 If Yes, what is their job title?</li> <li>Director of building grounds.</li> <li>114. Does the school practice IPM?</li> <li>✓ Yes</li> </ul>   |  |  |  |  |  |  |
| <ul> <li>Yes</li> <li>No</li> <li>113c.1 If Yes, what is their job title?</li> <li>Director of building grounds.</li> <li>114. Does the school practice IPM?</li> <li>✓ Yes</li> <li>No</li> <li>114a. Is vegetation kept one foot away from the building?</li> <li>✓ Yes</li> </ul>         |  |  |  |  |  |  |
| <ul> <li>Yes</li> <li>No</li> <li>113c.1 If Yes, what is their job title?</li> <li>Director of building grounds.</li> <li>114. Does the school practice IPM?</li> <li>Yes</li> <li>No</li> <li>114a. Is vegetation kept one foot away from the building?</li> <li>Yes</li> <li>No</li> </ul> |  |  |  |  |  |  |
| <ul> <li>Yes</li> <li>No</li> <li>113c.1 If Yes, what is their job title?</li> <li>Director of building grounds.</li> <li>114. Does the school practice IPM?</li> <li>✓ Yes</li> <li>No</li> <li>114a. Is vegetation kept one foot away from the building?</li> <li>✓ Yes</li> </ul>         |  |  |  |  |  |  |

Page 46 of 48 06/03/2016 09:36 AM

# 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Status Date: 12/16/2015 10:45 AM

Indoor Air Quality

(No Response)

| Page Last Modified: 03/16/2016   |
|--|
| 114c. Is there a certified pesticide applicator on staff?  |
| <ul><li>✓ Yes</li><li>□ No</li></ul>   |
| 114d. Are pesticides used in the building?   |
| ✓ Yes  □ No  |
| 114d.1 If Yes, how are they typically applied?   |
| <ul> <li>☑ Spot treatment</li> <li>☐ Area wide treatments</li> </ul>   |
| 114e. Are pesticides used on the grounds?  |
| ☐ Yes ☑ No   |
| 114e.1 If Yes, was an emergency exemption granted by the Board of Education?   |
| □ Yes □ No   |
| <ul> <li>115. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?</li> <li>□ Yes</li> <li>☑ No</li> </ul>  |
| 115a. Has the facility been tested for the presence of radon?  |
| ✓ Yes  □ No  |
| 115b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?   |
| ☐ Yes ☑ No   |
| 115c. If Yes, did the school take steps to mitigate the elevated radon levels?   |
| <ul> <li>Yes, active mitigation system installed</li> <li>Yes, passive mitigation system made active</li> <li>Yes, ventilation controls (HVAC) adjusted</li> <li>Yes, other (describe)</li> <li>No action taken</li> </ul> |
| 115c.1 Describe other actions taken to mitigate elevated radon levels:   |

Page 47 of 48 06/03/2016 09:36 AM

## 2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

American Red Cross

Page Last Modified: 03/16/2016

#### **American Red Cross Shelter**

116. American Red Cross Shelter

| Yes |  |  |  |
|-----|--|--|--|
| No  |  |  |  |

06/03/2016 09:36 AM Page 48 of 48