2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Information

Page Last Modified: 06/02/2016

Building Information

1. Name of School District:

BROCKPORT CSD

2. SED District 8-Digit BEDS Code:

261801060000

20100100000
3. Building Name:
Brockport Grounds Building
4. SED 4-Digit Facility Code:
3012
5. Survey Inspection Date:
09/02/2015
6. Building 911 Address:
40 Allen Street Building 201
7. City:
Brockport
8. Zip Code:
14420
9. Certificate of Occupancy Status:
☑ A - Annual
□ T - Temporary □ N - None
10. Certificate of Occupancy Expiration Date:
01/01/2017 Building Age, Gross Square Footage and Maintenance Staff
11. Year of Original Building:
1996
12. Gross square ft. of Building as currently configured:
7,200
13. Number of Floors:

14. How many full-time and part-time custodians are employed at the school (or work in the building)?

1

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Information

Page Last Modified: 06/02/2016

	Count Employees
Full-time custodians:	0
Part-time custodians:	0
Totals:	

Building Ownership and Occupancy Status

- 15. Building Ownership (check one):
- Owned and used by district
- Owned by District and leased to non-district entity
- Owned by District, part used by district, part leased to non-district entity
- Owned by non-district entity and leased to district

16. For which of the following purposes is the building currently used? (check all that apply)

- □ Used for student instructional purposes
- Used for district administration
- \blacksquare Used for other district purposes
- \Box Used by other organization(s)

16a. Describe use for other district purposes:

Building Maintenance & Operations Storage

Building Users

17. How many students were registered to receive instruction in this building as of October 1, 2014? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)

0

18. Of these registered students, how many receive most of their instruction in:

	Quantity
18a. Permanent instructional spaces (i.e., regular classrooms)	0
18b. Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	0
18c. Non-instructional spaces used as instructional spaces	0

18c.1 If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2014? (check all that apply)

- □ Cafeteria
- Gymnasium
- □ Administrative Spaces
- Library
- □ Lobby
- □ Stairwell
- □ Storage space
- □ Other (please describe)
- None

```
19. Grades Housed:
```

N/A

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Information

Page Last Modified: 06/02/2016

20. For how many instructional days during the 2013-14 school year (July 1 through June 30, was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")
0
21. Is the building used for instructional purposes in the summer?
Yes
No
22. Have there been renovations or construction in the building during the past 12 months?
Yes
No
23. Was major construction/renovation work since 2010 conducted when school was in session?
Yes

🗹 No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Program Spaces

Page Last Modified: 03/17/2016

Program Spaces

:	24.	Number of instructional	classrooms:					
(0							
	0							
2	25.	Gross square footage of all instructional classrooms (combined):						
(0.00	0						
:	26.	Other spaces provided:	(check all that ar	oply)				
		 a. N/A (none) b. Administration c. Art d. Audio Visual e. Auditorium f. Cafeteria g. Computer Ro h. Guidance i. Gymnasium 		 j. Health Office k. Home & Careers l. Kitchen m. Large Group Instruction n. Library o. Multipurpose Rooms p. Music q. Pre-K r. Remedial Rooms 		 s. Resource Rooms t. Science Labs u. Special Education v. Swimming Pool w. Teacher Resource x. Technology/Shop y. Other (please describe) 		
		26y. Describe other sp						
		(No Response)						
Space	Ade	quacy						
:	27.	Rating of space adequa	cy:					
8	⊒ F	ood air oor						
		27a. Enter comments:						
		(No Response)						
	28.	Estimated capital const	ruction expenses	s anticipated for this build	ling th	ough 2020-2021 school year		
				the building inspection is				
	74,00	00						
	,							
C 8 1	⊡ S ⊐ U	Overall building rating (xcellent atisfactory insatisfactory oor	to be answered a	after the building inspection	on is c	omplete)		
	30.	Was overall building rat	ing established a	after consultation with hea	alth an	d safety committee?		
	⊐ Y ⊒ N	es 0						
A/E Inf	orm	ation:						
:	31.	A/E Firm Name:						

Labella Associatoes, DPC

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Program Spaces

Page Last Modified: 03/17/2016

32. A/E Firm Address:

300 State Street, Suite 201 Rochester, NY 14614

33. A/E Firm Phone Number:

5854546110

34. E-mail:

dpieters@labellapc.com

35. A/E Name:

Daniel Pieters

36. A/E License #:

032927

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

Page Last Modified: 06/02/2016

Site Utilities

37. W	/ater
☑ Y	
	37a. Type of Service:
	 Municipal or Utility provided Well Other
	37b. Condition:
	 Excellent Satisfactory Unsatisfactory Non-Functioning Critical Failure
	37c. Year of Last Major Reconstruction/Replacement:
	1996
	37d. Expected Remaining Useful Life (Years):
	20
	37e. Cost to Reconstruct/Replace \$:
	(No Response)
	37f. Comments:
	(No Response)
38.	Site Sanitary (H)
☑ Y	
	38a. Type of Service: Image: Municipal or utility sewer Image: Site septic Image: Other
	38b. Condition:
	 Excellent Satisfactory Unsatisfactory Non-Functioning Critical Failure
	38c. Year of Last Major Reconstruction/Replacement:
	1996

38d. Expected Remaining Useful Life (Years):

20

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities Page Last Modified: 06/02/2016 38e. Cost to reconstruct/Replace \$: (No Response) 38f. Comments: (No Response) 39. Site Gas (H) Yes □ No 39a. Type of gas service: Natural Gas Liquid Petroleum 39b. Condition: □ Excellent ☑ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure 39c. Year of Last Major Reconstruction/Replacement; 1996 39d. Expected Remaining Useful Life (Years): 20 39e. Cost to Reconstruct/Replace \$: (No Response) 39f. Comments: (No Response) 40. Site Fuel Oil (H) □ Yes ☑ No 41. Site Electrical, Including Exterior Distribution (H) Yes □ No 41a. Service Provider: □ Municipal or utility provided □ Self-Generated

- ☑ Other
- □ N/A

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

Page Last Modified: 06/02/2016

	41b. Type of Service:
	Above Ground
	Below Ground
	□ N/A
	41c. Condition:
	Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	Critical Failure
	41d. Year of Last Major Reconstruction/Replacement:
	1996
	41e. Expected Remaining Useful Life (Years):
	5
	41f. Cost to Reconstruct/Replace \$:
	5,000.00
	41g. Comments:
	Needs additional service capacity.
Stormwater	Management
42. C	Closed Drainage Pipe Stormwater Management System

42a. Does this facility have a closed pipe system?

YesNo

42b. Condition:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

42c. Year of Last Major Reconstruction/Replacement:

1996

42d. Expected Remaining Useful Life (Years):

20

42e. Cost to Reconstruct/Replace \$:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

Page Last Modified: 06/02/2016

42f. Comments:

(No Response)

43. Open Drainage Pipe Stormwater Management System

43a. Does this facility have an open stormwater system (ditch)?

□ Yes

🗹 No

44. Catch Basins/Drop Inlets/Manholes

44a. Does this facility have catch basins/drop inlets/manholes?

Yes

□ No

44b. Condition:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

44c. Year of Last Major Reconstruction/Replacement:

1996

44d. Expected Remaining Useful Life (Years):

20

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

(No Response)

45. Culverts

45a. Does this facility have culverts?

□ Yes

🗹 No

46. Outfalls

46a. Does this facility have outfalls?

□ Yes

🗹 No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Site Utilities

Page Last Modified: 06/02/2016

47. Infiltration Basins/Chambers

47a. Does this facility have infiltration basins/chambers?

- □ Yes
- 🗹 No

48. Retention Basins

- 48a. Does this facility have retention basins?
- □ Yes
- 🗹 No

49. Wetponds

- 49a. Does this facility have wetponds?
- □ Yes
- 🗹 No

50. Manufactured Stormwater Proprietary Units

50a. Does this facility have proprietary units?

- □ Yes
- 🗹 No

51. Point of Outfall Discharge: (check all that apply)

- □ Municipal storm sewer system
- Combined sewer system
- □ Surface Water
- On-site recharge
- □ Other (describe)
- Not Applicable

52. Outfall Reconnaissance Inventory

Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?

- □ Yes
- ☑ No
- □ Not Applicable

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Other Site Features

Page Last Modified: 06/02/2016

Other Site Features

- 53. Pavement (Roadways and Parking Lots)
- 🗹 Yes
- □ No

53a. Type: (check all that apply)

- □ Concrete
- 🗹 Asphalt
- □ Gravel
- □ Other
- □ None

53b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- □ Non-Functioning
- Critical Failure

53c. Year of Last Major Reconstruction/Replacement:

1996

53d. Expected Remaining Useful Life (Years):

5

53e. Cost to Reconstruct/Replace \$:

142,931.00

53f. Comments:

Mill and repave.

54. Sidewalks

🗹 Yes

□ No

54a. Type: (check all that apply)

- ☑ Concrete
- □ Asphalt
- □ Paver
- □ Other

54b. Condition:

- Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- Non-Functioning
- Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Other Site Features

Page Last Modified: 06/02/2016

54c. Year of Last Major Reconstruction/Replacement:

1996

54d. Expected Remaining Useful Life (Years):

20

54e. Cost to Reconstruct/Replace \$:

(No Response)

54f. Comments:

(No Response)

- 55. Playgrounds and Playground Equipment
- □ Yes
- 🗹 No

56. Athletic Fields and Play Fields

- □ Yes
- 🗹 No

56f. Does the facility have synthetic turf field(s)

- □ Yes
- 🗹 No

56f.1 If Yes, how many synthetic turf fields?

(No Response)

56f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):

(No Response)

56f.3 Type of synthetic turf field infill:

(No Response)

- 57. Exterior Bleachers / Stadiums
- □ Yes
- 🗹 No

58. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)

□ Yes

🗹 No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Substructure

Page Last Modified: 06/02/2016

Substructure

- 59. Foundation (S)
 - 59a. Type (check all that apply):
- Reinforced Concrete
- □ Masonry on Concrete Footing
- □ Other

59b. Evidence of structural concerns (check all that apply):

- Structural Cracks
- □ Heaving/Jacking
- □ Decay/Corrosion
- □ Water Penetration
- Unsupported Ends
- □ Other
- None

59c. Condition:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

59d. Year of Last Major Reconstruction/Replacement:

1995

59e. Expected Remaining Useful Life (Years):

70

59f. Cost to Reconstruct/Replace \$:

(No Response)

59g. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page Last Modified: 06/02/2016

BUILDING ENVELOPE

60. Structural Floors (S)

60a. Type (check all that apply):

- Reinforced Concrete Slab on Grade
- Concrete/Metal Deck/Metal Joists
- Precast Concrete Structural System
- □ Wood Deck on Wood Trusses
- Wood Deck on Wood Joists
- Concrete Deck on Wood Structure
- \Box Other (specify)

60b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

□ Structural Cracks

- Unsupported Ends
- □ Rot/Decay/Corrosion
- □ Deflection
- □ Seriously Damaged/Missing Components
- Other Problems
- None

60b.1 Describe Other Problems:

(No Response)

60c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- □ Cracks
- □ Deflection
- □ Rot/Decay/Corrosion
- None

60d. Overall Condition of Structural Floors:

- Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

60e. Year of Last Major Reconstruction/Replacement:

1996

60f. Expected Remaining Useful Life (Years):

25

60g. Cost to Reconstruct/Replace \$:

(No Response)

60h. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page Last Modified: 06/02/2016

61. Exterior Walls/Columns (S)

61a. Material (check all that apply):

- □ Concrete
- □ Masonry
- ✓ Steel
- ☑ Wood
- □ Other (specify)

61b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply):

- □ Structural Cracks
- Rot/Decay/Corrosion
- Other Problems
- None

61b.1 Describe Other Problems:

(No Response)

61c. Evidence of Concerns with Exterior Cladding (check all that apply):

- Cracks/Gaps
- □ Inadequate Flashing
- □ Efflorescence
- Moisture Penetration
- □ Rot/Decay/Corrosion
- Other Problems
- None

61c.1 Describe Other Problems:

(No Response)

61d. Overall Condition of Exterior Walls/Columns:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

61e. Year of Last Major Reconstruction/Replacement:

1996

61f. Expected Remaining Useful Life (Years):

40

61g. Cost to Reconstruct/Replace \$:

(No Response)

61h. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page Last Modified: 06/02/2016

	62a. Material (check all that apply):
	Masonry
	□ Concrete ☑ Metal
	Wood
	□ Other
	62a.1 Specify other:
	(No Response)
	62b. Overall Condition of Chimneys:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	 Non-Functioning Critical failure
	62c. Year of Last Major Reconstruction/Replacement:
	62.d Expected Remaining Useful Life (Years):
	10
	62e. Cost to Reconstruct/Replace \$:
	(No Response)
	62f. Comments:
	Some PVC flues
63	Parapets (S)
јј. Цара	

64a. Overall Condition of Exterior Door Units:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page Last Modified: 06/02/2016

64b.	Overall	condition of	exterior	door	hardware:	

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

64c. Do any exterior doors have magnetic locking devices?

□ Yes

🗹 No

64d. Safety/Security features are adequate?

🗹 Yes

□ No

64e. Year of Last Major Reconstruction/Replacement:

1996

64f. Expected Remaining Useful Life (Years):

10

64g. Cost to Reconstruct/Replace \$:

(No Response)

64h. Comments:

(No Response)

65. Exterior Steps, Stairs, Ramps (S)

□ Yes

🗹 No

66. Fire Escapes (S)

66a. Does This Facility Have One or More Fire Escapes?

□ Yes

🗹 No

67. Windows

□ Yes

🗹 No

Roof and Skylights (S)

68. Roof and Skylights (S)

🗹 Yes

□ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page Last Modified: 06/02/2016

68a. Type of roof construction (check all that apply):

- □ Metal deck on metal trusses/joists
- ☑ Wood deck on wood trusses/joists
- □ Wood deck on metal trusses/joists
- □ Concrete on metal deck on metal trusses/joists
- □ Other (describe below)

68a.1 Other roof construction type:

(No Response)

68b. Type of roofing material (check all that apply):

- □ Single-ply membrane
- □ Built-up
- ☑ Asphalt shingle
- Pre-formed metal
- □ IRMA
- □ Slate
- □ Other (describe below)

68b.1 Other roofing material:

(No Response)

68c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- □ Structural cracks
- Unsupported ends
- □ Rot/Decay/Corrosion
- □ Deflection
- □ Seriously damaged/missing components
- □ Other concerns (describe)
- None

68c.1 Describe other concerns:

(No Response)

68d. Evidence of structural concerns with roof deck (check all that apply):

- Cracks
- Deflection
- □ Rot/Decay/Corrosion
- None

68e. Does this facility have skylights?

- □ Yes
- 🗹 No

68f. Skylight material (check all that apply):

- Plastic
- □ Glass
- □ Other
- ☑ N/A

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Building Envelope

Page Last Modified: 06/02/2016

68g. Overall condition of skylights:

- □ Excellent
- □ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

68h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- □ Failures/Splits/Cracks
- □ Rot/Decay/Corrosion
- □ Inadequate flashing/curbs/pitch pockets
- □ Inadequate or poorly functioning roof drains
- Evidence of water penetration/active leaks
- □ Other (specify)
- ☑ None

68h.1 Specify other concerns:

(No Response)

68i. Overall Condition of Roof and Skylights:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

68j. Year of Last Major Reconstruction/Replacement:

1996

68k. Expected Remaining Useful Life (Years):

5

68I. Cost to Reconstruct/Replace \$:

(No Response)

68m. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 06/02/2016

INTERIOR SPACES

69. Interior Bearing Walls and Fire Walls (S)

□ Yes

No

Other Interior Walls

70. Other Interior Walls

🗹 Yes

□ No

70a. Overall condition of other interior walls:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

70b. Year of Last Major Reconstruction/Replacement:

1996

70c. Expected Remaining Useful Life (Years):

15

70d. Cost to Reconstruct/Replace \$:

(No Response)

70e. Comments:

(No Response)

Floor Finishes

71. Carpet

□ Yes

- 🗹 No
- 72. Resilient Tiles or Sheet Flooring
- 🗹 Yes
- □ No

72a. Where located (check all that apply):

- Instructional Space
- Common Area

72b. Overall condition of resilient tiles or sheet flooring:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 06/02/2016

	72d. Expected Remaining Useful Life (Years):
	5
	72e. Cost to Reconstruct/Replace \$:
	(No Response)
	72f. Comments:
	(No Response)
3.	Hard Flooring (concrete; ceramic tile; stone; etc)
e y I n	'es Io
	 73a. Where located (check all that apply): Instructional Space
	 ✓ Common Area
	73b. Overall condition of hard flooring:
	 Satisfactory Unsatisfactory
	 Non-Functioning Critical Failure
	73c. Year of Last Major Reconstruction/Replacement:
	1996
	73d. Expected Remaining Useful Life (Years):
	5
	73e. Cost to Reconstruct/Replace \$:
	(No Response)
	73f. Comments:
	(No Response)
4.	Wood Flooring

75. Ceilings (H)

- 🗹 Yes
- □ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 06/02/2016

75a. Overall condition of ceilings:

- Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

1996

75c. Expected Remaining Useful Life (Years):

20

75d. Cost to Reconstruct/Replace \$:

(No Response)

75e. Comments:

(No Response)

Lockers

76. Lockers

□ Yes

🗹 No

76d. Cost to Reconstruct/Replace \$:

(No Response)

Interior Doors

77. Interior Doors

🗹 Yes

□ No

77a. Overall condition of interior door units:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

77b. Overall condition of interior door hardware:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

77c. Year of Last Major Reconstruction/Replacement:

1996

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 06/02/2016

77d. Expected Remaining Useful Life (Years):

8

77e. Cost to Reconstruct/Replace \$:

(No Response)

77f. Comments:

(No Response)

Interior Stairs (S)

78. Interior Stairs (S)

□ Yes

🗹 No

Elevator, Lifts and Escalators (H)

79. Elevator, Lift, and Escalators (H)

□ Yes

🗹 No

Interior Electrical Distribution (H)

```
80. Interior Electrical Distribution (H)
```

```
☑ Yes□ No
```

80a. Interior electrical supply meets current needs:

YesNo

80b. Condition of interior electrical distribution:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

80c. Year of Last Major Reconstruction/Replacement:

```
1995
```

80d. Expected Remaining Useful Life (Years):

10

80e. Cost to Reconstruct/Replace \$:

(No Response)

80f. Comments:

(No Response)

Lighting Fixtures

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 06/02/2016

81.	Interior Lighting Fixtures
	/es No
	81a. Condition of interior lighting fixtures:
	 Excellent Satisfactory Unsatisfactory Non-Functioning Critical Failure
	81b. Year of Last Major Reconstruction/Replacement:
	81c. Expected Remaining Useful Life (Years):
	81d. Cost to Reconstruct/Replace \$:
	(No Response) 81e. Comments:
	(No Response)
munio	cation Systems (H)
	Communication Systems (H) Ves No
	82a. Communication systems are adequate:
	 ✓ Yes □ No
	82b. Condition of communication systems:
	 Excellent Satisfactory Unsatisfactory Non-Functioning Critical Failure
	82c. Year of Last Major Reconstruction/Replacement:
	1995
	82d. Expected Remaining Useful Life (Years):
	10
	82e. Cost to Replace/Reconstruct \$:
	(No Response)
	82f. Comments:
	(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 06/02/2016

Swimming Pool and Swimming Pool Systems

- 83. Swimming Pool and Swimming Pool Systems
- □ Yes
- 🗹 No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Plumbing (Excluding HVAC Systems)

Page Last Modified: 03/17/2016

PLUMBING

84.	Water	Distribution	System	(H)
-----	-------	--------------	--------	-----

✓ Yes

□ No

84a. Types of pipes (check all that apply):

- □ Iron
- □ Galvanized
- Copper
- □ Lead
- D PVC
- □ Other

84b. Overall condition of water distribution system:

- Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

84c. Year of Last Major Reconstruction/Replacement:

1996

84d. Expected Remaining Useful Life (Years):

18

84e. Cost to Reconstruct/Replace \$:

(No Response)

84f. Comments:

(No Response)

Plumbing Drainage System (H)

85. Plumbing Drainage System (H)

☑ Yes

□ No

85a. Types of pipes (check all that apply):

- □ Iron
- □ Galvanized
- Copper
- □ Lead
- D PVC
- □ Other

85b. Overall condition of drainage system:

- Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Plumbing (Excluding HVAC Systems)

Page Last Modified: 03/17/2016

85c. Year of Last Major Reconstruction/Replace	cement:
--	---------

1996

85d. Expected Remaining Useful Life (Years):

18

85e. Cost to Reconstruct/Replace \$:

(No Response)

85f. Comments:

(No Response)

Hot Water Heaters (H)

86. Hot Water Heaters (H)

Yes

□ No

86a. Type of fuel (check all that apply):

- 🗆 Oil
- Natural Gas
- Electricity
- □ Propane
- □ Other

86b. Overall condition of hot water heaters:

- Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

86c. Year of Last Major Reconstruction/Replacement:

1996

86d. Expected Remaining Useful Life (Years):

18

86e. Cost to Reconstruct/Replace \$:

(No Response)

86f. Comments:

(No Response)

Plumbing Fixtures

87. Plumbing Fixtures

🗹 Yes

□ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Plumbing (Excluding HVAC Systems)

Page Last Modified: 03/17/2016

87a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, etc):

□ Excellent

☑ Satisfactory

- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

87b. Year of Last Major Reconstruction/Replacement:

1996

87c. Expected Remaining Useful Life (Years):

20

87d. Cost to Reconstruct/Replace \$:

(No Response)

87e. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

HVAC Systems

Page Last Modified: 03/17/2016

HVAC SYSTEMS

88. HVAC Systems Type

88a. Does this building have a central HVAC system?

□ Yes

🗹 No

Heat Generating Systems (H)

```
88b.1 Other central HVAC system technology:
```

(No Response)

89. Heat Generating Systems (H)

YesNo

89a. Heat generation source (check all that apply):

- □ Boiler / Hot Water
- Boiler / Steam
- Furnace / Forced Air
- Unit Ventilation
- Geothermal
- □ Biomass
- □ Electric
- □ Other (describe below)

89a.1 Other heat generation source:

(No Response)

89b. Overall condition of heat generating systems:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

89c. Year of Last Major Reconstruction/Replacement:

1996

```
89d. Expected Remaining Useful Life (Years):
```

8

89e. Cost to Reconstruct/Replace \$:

(No Response)

89f. Comments:

(No Response)

Heating Fuel/Energy Systems (H)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

HVAC Systems

Page Last Modified: 03/17/2016

90. Heating Fuel / Energy Systems (H)
✓ Yes□ No
90a. Overall condition of heating fuel / energy systems:
 Excellent Satisfactory Unsatisfactory Non-Functioning Critical Failure
90b. Year of Last Major Reconstruction/Replacement:
1996
90c. Expected Remaining Useful Life (Years):
8
90d. Cost to Reconstruct/Replace \$:
(No Response)
90e. Comments:
(No Response)
Cooling/Air Conditioning Generating Systems
91. Cooling / Air-Conditioning Generating Systems
✓ Yes□ No
91a. Overall condition of cooling/air-conditioning generating systems:
Excellent
 Satisfactory Unsatisfactory
□ Non-Functioning
Critical Failure
91b. Year of Last Major Reconstruction/Replacement:
91c. Expected Remaining Useful Life (Years):
10 Old Cost to Reconstruct/Replace fr
91d. Cost to Reconstruct/Replace \$:
(No Response)
91e. Comments:
(No Response) AIR HANDLING AND VENTILATION EQUIPMENT

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

HVAC Systems

Page Last Modified: 03/17/2016

92.	Air Handling and Ventilation Equipment: Supply Units, Exhaust Units, Relief/Return Units, etc. (H)		
🗹 Ye	25		
	92a. Overall condition of air handling and ventilation systems:		
	□ Excellent		
	□ Satisfactory		
	☑ Unsatisfactory		
	□ Non-Functioning		
	Critical Failure		
92b. Year of Last Major Reconstruction/Replacement:			
	3		
	5		
	92d. Cost to Reconstruct/Replace \$:		
	(No Response)		
	92e. Comments:		
Poor ventilation in maintenance bay.			
d Heating and Cooling Distribution Systems			
93.	Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectorss, Traps, Insulation,		

Pi

- etc. (H)
- □ Yes
- ☑ No

Ducted Heating and Cooling Distrbution Systems

94. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)

Yes

□ No

94a. Overall condition of ducted heating and cooling distribution systems:

```
□ Excellent
```

- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

94b. Year of Last Major Reconstruction/Replacement:

1996

94c. Expected Remaining Useful Life (Years):

10

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

HVAC Systems

Page Last Modified: 03/17/2016

94d. Cost to Reconstruct/Replace \$:

(No Response)

94e. Comments:

(No Response)

HVAC Control Systems

95. HVAC Control Systems (H)

Yes

□ No

95a. Overall condition of control systems:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

95b. Year of Last Major Reconstruction/Replacement:

1996

95c. Expected Remaining Useful Life (Years):

10

95d. Cost to Reconstruct/Replace \$:

(No Response)

95e. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Fire Safety Systems

Page Last Modified: 03/17/2016

Fire Safety Systems

96. Fire Alarm Systems (H) Yes □ No 96a. Overall condition of fire alarm system: □ Excellent Satisfactory □ Unsatisfactory □ Non-Functioning Critical Failure 96b. Year of Last Major Reconstruction/Replacement: 1996 96c. Expected Remaining Useful Life (Years): 20 96d. Cost to Reconstruct/Replace \$: 5,000.00 96e. Comments: Replace devices with maintenance building system.

Smoke Detection System (H)

- 97. Smoke Detection Systems (H)
- Yes

□ No

97a. Overall condition of smoke detection systems:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

97b. Year of Last Major Reconstruction/Replacement:

1996

97c. Expected Remaining Useful Life (Years):

20

97d. Cost to Reconstruct/Replace \$:

5,000.00

97e. Comments:

Replace devices with maintenace building system

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Fire Safety Systems

Page Last Modified: 03/17/2016

Fire Suppression Systems

- 98. Fire Suppression Systems: Sprinklers, Standpipes, Kitchen Hoods, etc. (H)
- □ Yes
- 🗹 No

Emergency/Exit Lighting Systems

- 99. Emergency / Exit Lighting Systems (H)
- Yes
- □ No

99a. Overall condition of emergency / exit lighting systems:

- □ Excellent
- □ Satisfactory
- Unsatisfactory
- □ Non-Functioning
- Critical Failure

99b. Year of Last Major Reconstruction/Replacement:

1996

99c. Expected Remaining Useful Life (Years):

1

99d. Cost to Reconstruct/Replace \$:

5,000.00

99e. Comments;

Emergency lighting units not observed.

Emergency/Standby Power Systems

100. Emergency or Standby Power System (H)

```
□ Yes
```

🗹 No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Accessibility

Page Last Modified: 03/17/2016

ACCESSIBILITY

101. Exterior Accessible Route (H)

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

🗹 Yes

□ No

102. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an accessible interior route as specified above?

YesNo

103. Additional Information on Accessibility

If the building lacks accessible interior or exterior routes:

103a. Cost of improvements needed to provide accessible exterior and interior routes as specified above \$:

(No Response)

103b. Comments:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Environment/Comfort/Health

Page Last Modified: 03/17/2016

ENVIRONMENT/COMFORT/HEALTH

104. General Appearance

	104a.	Overall Rating:
~	Good	
	Fair	
	Poor	

104b. Comments:

(No Response)

105. Cleanliness

105a. Overall Rating:

- Good
- □ Fair
- D Poor

105b. Comments:

(No Response)

106. Are there walk off mats; grills in the entryway?

- □ Yes
- 🗹 No

107. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education?

- □ Yes
- 🗹 No

108. Lighting Quality:

108a. Types of lighting in general purpose classrooms (check all that apply):

- □ Daylight
- □ Flourescent-not full spectrum
- □ Flourescent full spectrum
- □ Incandescent
- ☑ Other (describe)

108a.1 Describe Other:

No classrooms.

108b. Are there blinds in the classroom to prevent glare?

□ Yes

🗹 No

108c. Overall Rating:

- □ Good
- 🗹 Fair
- D Poor

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Environment/Comfort/Health

Page Last Modified: 03/17/2016

108d. Comments:

(No Response)

109. Evidence of Vermin

109a. Is there evidence of active infestations of...(check all that apply)?

- □ Rodents
- □ Wood-boring or Wood-eating Insects
- □ Cockroaches
- Other Vermin
- None

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Indoor Air Quality

Page Last Modified: 03/17/2016

Indoor Air Quality

110. Mold

110a. Is there visible mold or moldy odors?

- □ Yes
- 🗹 No

110c. Are any surfaces constructed of any of the following materials?

- Paper-faced or gypsum products
- ☑ Cellulose products (typically ceiling tiles)

110d. Estimated cost of necessary improvements \$:

(No Response)

110d. Comments:

(No Response)

111. Humidity/Moisture

111a. Overall rating of humidity/moisture condition in building:

- Good
- 🗆 Fair
- □ Poor

111b. Are any of the following found in/or around classroom areas (check all that apply)?

- Active leaks in roof
- □ Active leaks in plumbing
- □ Moisture condensation
- □ Visible stains or water damage
- None None

111c. Are any of the following found in/or around other areas (check all that apply)?

- □ Active leaks in roof
- □ Active leaks in plumbing
- □ Moisture condensation
- □ Visible stains or water damage
- None
- 112. Ventilation: fresh air intake locations, air filters, etc.

112a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?

- □ Yes
- 🗹 No

112b. Is there accumulated dirt, dust or debris around fresh air intakes?

- □ Yes
- ☑ No

112c. Are fresh air intakes free of blockage?

- 🗹 Yes
- □ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Indoor Air Quality

Page Last Modified: 03/17/2016

112d. Is accumulated dirt, dust or debris in ductwork? □ Yes 🗹 No 112e. Are dampers functioning as designed? ✓ Yes □ No 112f. Condition of air filters: □ Good Fair □ Poor 112g. Outside air is adequate for occupant load: □ Yes 🗹 No 112h. Rating of ventilation/indoor air quality: □ Good 🗹 Fair □ Poor 112i. Comments: (No Response) 113. Indoor Air Quality (IAQ) Plan 113a. Does the school district use EPA's Tools for Schools program? 🗹 Yes □ No 113c. Has the District assigned IAQ responsibilities to a designated individual? Yes No 113c.1 If Yes, what is their job title? Director of Buildings & Grounds 114. Does the school practice IPM? Yes □ No 114a. Is vegetation kept one foot away from the building? 🗹 Yes □ No 114b. Are crevices and holes in walls, floors and pavement sealed or eliminated? ☑ Yes

□ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Indoor Air Quality

Page Last Modified: 03/17/2016

114c. Is there a certified pesticide applicator on staff?

- 🗹 Yes
- □ No

114d. Are pesticides used in the building?

- Yes
- □ No

114d.1 If Yes, how are they typically applied?

- ☑ Spot treatment
- Area wide treatments

114e. Are pesticides used on the grounds?

- □ Yes
- 🗹 No

114e.1 If Yes, was an emergency exemption granted by the Board of Education?

- □ Yes
- □ No

115. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?

Ye
16

🗹 No

115a. Has the facility been tested for the presence of radon?

- ☐ Yes
- 🗹 No

115b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- □ Yes
- □ No

115c. If Yes, did the school take steps to mitigate the elevated radon levels?

- □ Yes, active mitigation system installed
- □ Yes, passive mitigation system made active
- □ Yes, ventilation controls (HVAC) adjusted
- Yes, other (describe)
- □ No action taken

115c.1 Describe other actions taken to mitigate elevated radon levels:

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

American Red Cross

Page Last Modified: 03/17/2016

American Red Cross Shelter

116. American Red Cross Shelter

- □ Yes
- 🗹 No